

Tanning Facility Inspection Summary Report

Operation: STIL-BETCHA TAN (ID: 768045)
Facility Name: STIL-BETCHA TAN
Facility Code: 49-5394
Facility Address: 1403 Route 96, Waterloo, NY 13165

To the Attention of:

Donnie Stilwell
1403 Route 96
Waterloo, NY 13165

Inspection

Date: June 26, 2019 10:13 AM
Inspector: Melissa Brown (mbrown@co.seneca.ny.us)
Responsible Person: Missy Peters

Summary

| | |
|--|---|
| Number of Public Health Hazards Found: | 0 |
| Number of Public Health Hazards NOT Corrected: | 0 |
| Number of Other Violations Found: | 1 |

Each item found in violation is reported below along with the code requirement.

NO PUBLIC HEALTH HAZARDS REPORTED

RECORDS AND SIGNS

ITEM #18 WAS FOUND IN VIOLATION 1 TIME(S).

All or parts of the item are violations.

Code Requirements: Adequate device labels present on tanning equipment 72-1.9(c)(1)

Inspector Findings: Beds 2,3,4: exposure stickers have worn off over the years. Finding the recommended exposure time for each type/style of bed/booth and recreating them would be sufficient for patron notification. If purchasing new stickers is an option, it would be ideal to get the manufacture sticker rather than recreating it.

Additional Information Collected During Inspection

Permitted Capacity: 11 Beds

Observed Capacity: 8 Beds

7 **Number of Tanning Beds**

1 **Number of Tanning Booths**

0 **Number of Other Tanning Equipment**

Comments: Bed 6 and 9 are not currently working.



Inspector: Melissa Brown (mbrown@co.seneca.ny.us)



Received by: Missy Peters

Photo

Caption



Bed 3 Recommended exposure time worn off due to use over the years.