

Seneca County Department of Health
Environmental Services
31 Thurber Drive , Waterloo,, NY 13165
(315) 539 - 1945
jbates@co.seneca.ny.us

Temporary Residence Inspection -- Summary Report

Operation: GLASS MAGNOLIA (ID: 837318)
Facility Name: GLASS MAGNOLIA
Facility Code: 49-2809 Facility Email: nrudolph47@gmail.com
Facility Address: 8339-8347 MAIN STREET INTERLAKEN, NY 14847

To the Attention of:
WALTER, NANCY RUDOLPH
8339 MAIN STREET
INTERLAKEN , NY 14847- Owner/Operator Email: nrudolph@gmail.com

Inspection

Date: DEC 28, 2017 01:23 PM
Inspector: Melissa Brown (mbrown@co.seneca.ny.us)
Responsible Person: mailed
(email:)

Summary

Number of public health hazards found: 0
Number of public health hazards NOT corrected: 0
Number of other violations found: 0

Each item found in violation is reported below along with the code requirement.

NO VIOLATIONS WERE OBSERVED.

Code Requirements

Inspector Findings

Additional Information Collected During Inspection

Comments

Fire Extinguishers replaced due to recall by manufacture.

END of REPORT

[Submit# 352883] GLASS MAGNOLIA (ID837318) Inspection# 1002229048